

## United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
09/669,771	09/26/2000	Kouichi Mizukami	10517/73	3237
75	7590 07/26/2004		EXAMINER	
Kenyon & Kenyon			BOTTORFF, CHRISTOPHER	
One Broadway			Angunum	
New York, NY	10004		ART UNIT	PAPER NUMBER
			3618	
			DATE MAILED: 07/26/2004	

Please find below and/or attached an Office communication concerning this application or proceeding.

	Application No.	Applicant(s)				
	09/669,771	MIZUKAMI ET AL.				
Office Action Summary	Examiner	Art Unit				
	Christopher Bottorff	3618				
The MAILING DATE of this communic Period for Reply	ation appears on the cover sheet	with the correspondence address				
A SHORTENED STATUTORY PERIOD FO THE MAILING DATE OF THIS COMMUNIC  - Extensions of time may be available under the provisions of after SIX (6) MONTHS from the mailing date of this communication of the period for reply specified above is less than thirty (30)  - If NO period for reply is specified above, the maximum statu  - Failure to reply within the set or extended period for reply within the set or extended peri	ATION. 37 CFR 1.136(a). In no event, however, may incation. days, a reply within the statutory minimum of the latory period will apply and will expire SIX (6) Months, by statute, cause the application to become	a reply be timely filed  hirty (30) days will be considered timely.  ONTHS from the mailing date of this communication.  ABANDONED (35 U.S.C. § 133).				
Status						
1) Responsive to communication(s) filed	on <u>07 May 2004</u> .					
2a)☐ This action is <b>FINAL</b> . 2b	2a)☐ This action is <b>FINAL</b> . 2b)☒ This action is non-final.					
3) Since this application is in condition for allowance except for formal matters, prosecution as to the merits is						
closed in accordance with the practice	e under <i>Ex parte Quayle</i> , 1935 C	.D. 11, 453 O.G. 213.				
Disposition of Claims						
4)⊠ Claim(s) <u>1-6 and 10</u> is/are pending in	the application.					
4a) Of the above claim(s) is/are withdrawn from consideration.						
5) Claim(s) is/are allowed.						
6)⊠ Claim(s) 1-6 and 10 is/are rejected.						
7) Claim(s) is/are objected to.						
8) Claim(s) are subject to restricti	on and/or election requirement.					
Application Papers						
9)☐ The specification is objected to by the	Examiner					
10) The drawing(s) filed on is/are:		ο by the Examiner				
Applicant may not request that any objecti						
Replacement drawing sheet(s) including the	• ,	` '				
11) The oath or declaration is objected to						
Priority under 35 U.S.C. § 119	•					
•	orfonoismo maioniko condes 25 H O O	0.440(-) (-) (5)				
12) Acknowledgment is made of a claim fo a) All b) Some * c) None of:	or foreign phonty under 35 U.S.C.	. § 119(a)-(d) or (f).				
1. Certified copies of the priority d	naumants have been received					
	ocuments have been received in	Application No.				
3. Copies of the certified copies of						
application from the Internation		in received in this National Stage				
* See the attached detailed Office action		ot received				
	2 12 12 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	<del></del> -				
-						
Attachment(s)						
<ol> <li>Notice of References Cited (PTO-892)</li> <li>Notice of Draftsperson's Patent Drawing Review (PTO)</li> </ol>		v Summary (PTO-413) o(s)/Mail Date				
3) Information Disclosure Statement(s) (PTO-1449 or Pi Paper No(s)/Mail Date 5/7/04, 6/9/04.		f Informal Patent Application (PTO-152)				
J.S. Patent and Trademark Office PTOL-326 (Rev. 1-04)	Office Action Summary	Part of Paper No./Mail Date 26				

and the companies of companies of the control of th

Art Unit: 3618

### **DETAILED ACTION**

The amendment filed May 7, 2004 has been entered. Claims 7 and 8 are canceled. Claims 1-6 and 10 are pending.

#### Information Disclosure Statement

The information disclosure statements (IDSs) submitted on May 7, 2004 and June 9, 2004 were considered by the examiner.

## Claim Rejections - 35 USC § 112

The following is a quotation of the second paragraph of 35 U.S.C. 112:

The specification shall conclude with one or more claims particularly pointing out and distinctly claiming the subject matter which the applicant regards as his invention.

Claims 1-6 and 10 are rejected under 35 U.S.C. 112, second paragraph, as being indefinite for failing to particularly point out and distinctly claim the subject matter which applicant regards as the invention.

Claim 1 recites the limitation "the meter unit" in lines 19, 24-25, and 27-28. Claim 10 also recites the limitation "the meter unit" in lines 14, 19-20, and 22-23. There is insufficient antecedent basis for this limitation in the claims.

# Claim Rejections - 35 USC § 103

The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:

(a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and

Art Unit: 3618

the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.

Claims 1-6 and 10 are rejected under 35 U.S.C. 103(a) as being unpatentable over Ford Taurus & Mercury Sable Haynes Repair Manual (Taurus) in view of Takayama et al. US 6,119,060, Maue et al. US 5,785,532, and Toshihiro et al. JP 64-30856.

Taurus teaches a structure in a motor vehicle that includes an engine control computer (ECA; see the discussion in column 3 of page 6-1), a relay block (item 6 in figure 4.2 indicates the presence of relays within the vehicle), a junction box in a cabin of the vehicle (see the box housing the fuse unit in figure 4.1), an ABS actuator (see the discussion on page 9-16), a meter unit in the cabin (any instrument panel gauge), a partition wall that separates the engine room and the cabin from each other (depicted in figure 1.2b), and a brake system (depicted in figure 1.2b). These components are concentrated within the vehicle body.

Although the claims broadly define the generally centralized region, the disclosure suggests that the components are arranged along the longitudinal centerline of the vehicle. Taurus does not disclose the engine control computer, the relay block, the junction box, the meter unit, and the ABS actuator as being located in a generally centralized region as broadly defined in the claims, or along the centerline as suggested by the disclosure. Taurus does not disclose that the locations of the engine control computer, the relay block, the junction box, and the ABS actuator are the same when the vehicle is a right-hand drive vehicle as when the vehicle is a left-hand drive vehicle.

Art Unit: 3618

Taurus does not disclose that the engine control computer, the relay block, the junction box, and the meter unit are located at a substantially same height. Taurus does not disclose that the engine control computer, the relay block, and the ABS actuator are located on the engine room side of the partition wall. Taurus does not disclose each of the engine control computer, the relay block, the junction box, the meter unit, and the ABS actuator are connected via one of a plurality of harnesses, and some of the harnesses pass through holes formed in a generally central portion of the partition wall. Taurus also does not teach the junction box and relay block being constructed as an integral assembly and mounted at least partly in a cowl.

However, Takayama et al. teaches that the practice of concentrating electrical components along the longitudinal centerline and on a dash cross member of a vehicle was old and well known in the art at the time the invention was made. See figures 1 and 2; lines 30-34 of column 3; and lines 36-43 of column 17. From the teachings of Takayama et al., concentrating the above components of Taurus along the longitudinal centerline would have been obvious to one of ordinary skill in the art at the time the invention was made. This would improve the efficiency of the assembly process.

Locating these components along the centerline would necessarily locate the components within the generally centralized region of the vehicle as defined in the claims. In addition, locating these components along the centerline would necessarily ensure that there locations would be the same when the vehicle is a right-hand drive vehicle as when the vehicle is a left-hand drive vehicle.

Art Unit: 3618

Takayama et al. further teaches arranging the electrical components at a height that is substantially the same. See Figures 1 and 2; lines 30-34 of column 3; and lines 17-25 of column 9. Also, Takayama et al. also suggests connecting the components via harnesses. See Figures 68 and 69. From the further teachings of Takayama et al., locating the engine control computer, the relay block, the junction box, and the meter unit at a substantially same height would have been obvious to one of ordinary skill in the art at the time the invention was made. This would allow the components to be efficient assembled an electrically connected.

In addition, Maue et al. teaches that the practice of locating the engine control computer, the relay block, and the ABS actuator on the engine room side of the partition wall was old and well known in the art at the time the invention was made. See Figure 5; column 3, lines 20-22; and 28-36, and column 4, lines 11-12. Maue et al. also teaches that the practice of connecting electrical components via harnesses 80, 82 was old and well known in the art at the time the invention was made. See Figure 5 and column 3, lines 20-22 and 28-36.

From the teachings of Maue et al., locating the engine control computer, the relay block, and the ABS actuator of Taurus on the engine room side of the partition wall would have been obvious to one of ordinary skill in the art at the time the invention was made. This would allow these components to be serviceable from with in the engine compartment. From the further teachings of Maue et al., connecting each of the engine control computer, the relay block, the junction box, the meter unit, and the ABS actuator via one of a plurality of harnesses would have been obvious to one of ordinary skill in

g notes from the state of the second of the second of the second of the first of the first of the second of the first of the second of the sec

Art Unit: 3618

the art at the time the invention was made. This would enable the effective distribution of electricity to the components.

Furthermore, Toshihiro et al. teaches that the practice of connecting electrical components via harnesses 7, 12, with a harness passing through a hole 5d formed in a generally central portion of a partition wall 3, was old and well known in the art at the time the invention was made. See Figures 1 and 2. From the teachings of Toshihiro et al., connecting each of the engine control computer, the relay block, the junction box, the meter unit, and the ABS actuator via one of a plurality of harnesses, with some of the harnesses passing through holes formed in a generally central portion of a partition wall, would have been obvious to one of ordinary skill in the art at the time the invention was made. This would enable the effective distribution of electricity to the components, including the components on opposing sides of the partition wall.

Also, Toshihiro et al. further teaches a vehicle body having a cowl (fig.1 and 2) formed in the vicinity of a partition wall 3, and wherein a relay block (10) and a junction box (4) are formed as an integral assembly and mounted at least partly in the cowl. It would have been obvious to one of ordinary skill in the art, at the time the invention was made, to make the junction box and relay block of Taurus as an integral unit and place them within a cowl member in the vicinity of the partition wall, as taught by Toshihiro et al., because it would facilitate the check of wiring and the replacement of fuses (see Toshihiro, "Constitution").

Moreover, rearranging the placement of components within a vehicle would not modify their operation and represents an obvious design choice. See *In re Japikse*, 86

医水平性 副主持教育的名词复数有关的人物的 "我们的唯一,我们的唯一的谁的神奇,就是她的情况,她们是不知识的一个人,不是他还

Art Unit: 3618

USPQ 70 (CCPA 1950) and *In re Kuhle*, 188 USPQ 7 (CCPA 1975). This rearrangement would improve the efficiency of the assembly process.

## Response to Arguments

Applicant's arguments filed May 7, 2004 have been fully considered but they are not persuasive. Contrary to Applicants' assertion, the references do render obvious claims 1-6 and 10 as discussed in the above rejection.

#### Conclusion

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Christopher Bottorff whose telephone number is (703) 308-2183. The examiner can normally be reached on Mon.-Fri. 7:30 a.m. - 4:00 p.m..

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Brian Johnson can be reached on (703) 308-0885. The fax phone number for the organization where this application or proceeding is assigned is 703-872-9306.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only.

Art Unit: 3618

Page 8

For more information about the PAIR system, see http://pair-direct.uspto.gov.

Should you have questions on access to the Private PAIR system, contact the

Electronic Business Center (EBC) at 866-217-9197 (toll-free).

**Christopher Bottorff** 

CHRISTOPHER P. ELLIS SUPERVISORY PATENT EXAMINER TECHNOLOGY CONTER 3600